Standard End Machining

Cross Drilled Hole

Male Thread

Female Thread

Standard Break Edge

Turned Journal

Hex Drive End

Square End


Single Flat

Double Flat


Ground Journal




Cross Drilled Hole




Standard Break Edge




Male Thread —BREAK EDGE 0.020 MAX — THREAD CALLOUT —





Female Thread THREAD CALLOUT




Hex Drive End








Square Drive End





Ground Journal

